

close print

Brand: **Holiday Inn**

Scheme: Tribute

Area: Guest Rooms

Category: WindowTreatments

Item: Drapery

Item Code: T-601

**Vendor:** Quiltcraft

**Model:** See Info Below

**Description:** Drapery Treatment

**Pattern:** See Below

**Color:** See Below

**Style:**

#### Specifications:

**Description:** Fixed full-length side panels flanking window; tailored valance across full width of treatment; separate full-length sheers and blackout draperies (black-out treatment against window). Shorter sheers and black-outs acceptable with HVAC/PTAC units.

**Finished Size:** To be verified on-site

#### Fabrics: Fabric at Side Panels and Valance

**Manufacturer:** [Valley Forge](#)  
**Phone:** (954) 971-1776

**Pattern:** Ice Satin, D03-36  
**Color:** Mushroom  
**Content:** 100% Avora (i.e. Burlington 7156 or equivalent)  
**Weight:** Approximately 6.3 oz. (per lin. yard)  
**Width:** 54"  
**Repeat:** N/A (Solid)

**Applications:** Overdrapery Fabric for T-601


#### Sheer Fabric

**Manufacturer:** [Valley Forge](#)  
**Phone:** (954) 971-1776

**Pattern:** Sleepy Stripe (Stripes to run horizontal)  
**Color:** Custom White  
**Content:** 100% Polyester  
**Weight:**  
**Width:** 118"  
**Repeat:** Vertical: 1-3/4" / Horizontal: 0"

**Applications:** Sheer Fabric for T-601

- General Notes:**
1. Fabricator to verify all site conditions, dimensions, and materials required for installation.
  2. Available as fabric inclusive or COM.
  3. See [Holiday Inn Window Treatment Preamble](#) for complete specs.



\$ \*\*\*\*\*

\$ \*\*\*\*\*

#### **Vendor Contact:**

Quiltcraft  
1230 East Ledbetter

Dallas, TX 75216-6988  
USA

David Pearson  
Sales Associate  
TEL: 214-376-1841  
FAX: 214-376-1852  
dpearson@quiltcraft.com

Prices above do not include taxes, shipping, or installation costs unless otherwise stated. All installed fabrics, upholstery, carpet, wall covering and other finish materials must meet local fire codes and regulations; Owner and Purchasing Agent must provide all code information to manufacturer. Fabricator and/or installer must confirm exact quantities required. Manufacturers must provide maintenance instructions.

© 2012 InterContinental Hotels Group. All rights reserved.

Last Update: 2009-08-24, Original Issue: 2006-01-01 ID:395

|