

[close](#) [print](#)

Brand: **Holiday Inn**  
 Scheme: Tribute  
 Area: Guest Rooms  
 Category: WindowTreatments  
 Item: Drapery  
 Item Code: T-601

Vendor: Quiltcraft  
 Model: See Info Below  
 Description: Drapery Treatment  
 Pattern: See Below  
 Color: See Below  
 Style:

#### Specifications:

**Description:** Fixed full-length side panels flanking window; tailored valance across full width of treatment; separate full-length sheers and blackout draperies (black-out treatment against window). Shorter sheers and black-outs acceptable with HVAC/PTAC units.

**Finished Size:** To be verified on-site

#### Fabrics: Fabric at Side Panels and Valance

**Manufacturer:** [Valley Forge](#)  
**Phone:** (954) 971-1776  
**Pattern:** Ice Satin, D03-36  
**Color:** Mushroom  
**Content:** 100% Avora (i.e. Burlington 7156 or equivalent)  
**Weight:** Approximately 6.3 oz. (per lin. yard)  
**Width:** 54"  
**Repeat:** N/A (Solid)


**Applications:** Overdrapery Fabric for T-601

#### Sheer Fabric

**Manufacturer:** [Valley Forge](#)  
**Phone:** (954) 971-1776  
**Pattern:** Sleepy Stripe (Stripes to run horizontal)  
**Color:** Custom White  
**Content:** 100% Polyester  
**Weight:**  
**Width:** 118"  
**Repeat:** Vertical: 1-3/4" / Horizontal: 0"

**Applications:** Sheer Fabric for T-601

- General Notes:**
1. Fabricator to verify all site conditions, dimensions, and materials required for installation.
  2. Available as fabric inclusive or COM.
  3. See [Holiday Inn Window Treatment Preamble](#) for complete specs.



\$ \*\*\*\*\*  
 \$ \*\*\*\*\*

#### Vendor Contact:

Quiltcraft  
 1230 East Ledbetter

Dallas, TX 75216-6988  
 USA

David Pearson  
 Sales Associate  
 TEL: 214-376-1841  
 FAX: 214-376-1852  
 dpearson@quiltcraft.com

Prices above do not include taxes, shipping, or installation costs unless otherwise stated. All installed fabrics, upholstery, carpet, wall covering and other finish materials must meet local fire codes and regulations; Owner and Purchasing Agent must provide all code information to manufacturer. Fabricator and/or installer must confirm exact quantities required. Manufacturers must provide maintenance instructions.